

Customer (Brent Lemons) - 02/28/2010 07:14 PM

We had a large ice storm in January here in Oklahoma, and I am just now starting to collect what's left...which is not much but pieces. I thought you would like to see what is left of the DX Engineering choke balun I got a while back - can you guys make it tougher??

Haaaa - just kidding! It came out pretty good considering it fell 85 ft and the coax didn't!!! The insides are intact except for the SO-239 connector still attached to the coax. Anyway, I thought you would like to see it. I lost 7 antennas in all.

It's always interesting to see how stuff holds up

73

Brent
KK5O



At left - still working! Replaced SO-239 connector and pressed back into service until replacement arrived.

(Replacement arrived - THANKS!)